















CP30				
Rodzaje profili		Wydajność [mm]	Średnica zwinięcia [mm]	Uwagi
1.		20x6 50x10	200 350	S/O
2.		30x6 80x15	200 350	S/O
3.		10 30	100 600	S/O
4.		50x30x3	800	S
5.		40x40x3	800	S
6.		20x20x3 50x50x7	250 400	S
7.		20x20x3 50x50x7	250 400	S
8.		30x15x4 50x25x5	250 350	S
9.		50x25x5	400	S
10.		10 30	100 600	O
11.		3/8" (17.2x2.3) 1-1/2" (48.3x2.9)	150 400	O
12.		40x40x5	350	O
13.		40x40x5	350	O
14.		60x1.5	800	O

Oznaczenia:

S - rolki standardowe

O - rolki opcjonalne

S/O - do prac seryjnych niezbędne jest wyposażenie maszyny w rolki opcjonalne