


















<b>CP40</b>				
<b>Rodzaje profili</b>		<b>Wydajność [mm]</b>	<b>Średnica zwinięcia [mm]</b>	<b>Uwagi</b>
1.		20x5 60x10	200 400	S/O
2.		50x10 100x15	200 350	S/O
3.		10 35	200 500	S
4.		20x10x1.5 60x40x3	250 1200	S/O
5.		20x20x1.5 50x50x3	250 1200	S/O
6.		20x20x3 60x60x6	200 500	S
7.		20x20x3 60x60x6	200 500	S
8.		30x15x3 80x45x6	250 600	S/O
9.		40x20x3 80x45x6	300 600	S/O
10.		40x20x3 60x30x6	400 800	S/O
11.		10 35	200 500	O
12.		1/2" (21.3x2.3) 2" (60.3x2.9) 70x1.5	200 800 1200	O
13.		25x25x3 50x50x6	250 400	O
14.		25x25x3 50x50x6	350 500	O
15.		10 35	180 500	O
16.		30x15x1.5 80x30x3	250 1500	O
17.		38 50	600 600	O

Oznaczenia:

S - rolki standardowe

O - rolki opcjonalne

S/O –do prac seryjnych niezbędne jest wyposażenie maszyny w rolki opcjonalne