
















<b>CPS50</b>				
<b>Rodzaje profili</b>		<b>Wydajność [mm]</b>	<b>Średnica zwinięcia [mm]</b>	<b>Uwagi</b>
1.		70x12	400	S/O
2.		110x15	350	S/O
3.		40	600	S/O
4.		70x40x3	1000	S/O
5.		50x50x4	800	S/O
6.		60x60x6	500	S
7.		60x60x6	500	S
8.		UPN100	600	S/O
9.		UPN100	600	S/O
10.		UPN80	1200	S
11.		40	600	O
12.		2-1/2" (76.1x3.2) 80x3	600 800	O
13.		60x60x6	600	O
14.		60x60x6	600	O
15.		100x40x3	2500	O

Oznaczenia:

S - rolki standardowe

O - rolki opcjonalne

S/O - do prac seryjnych niezbędne jest wyposażenie maszyny w rolki opcjonalne