















Z402				
Rodzaje profili		Wydajność [mm]	Średnica zwinięcia [mm]	Uwagi
1.		60x10	600	S
2.		100x15	400	S
3.		35	600	S
4.		60x40x3	1400	S
5.		50x50x3	1400	S
6.		60x60x6	700	S
7.		60x60x6	700	S
8.		80x40x6	600	S
9.		80x45x6	600	S
10.		60x30x6	1000	S
11.		35	600	O
12.		2" (60.3x2.9)	600	O
13.		50x50x5	500	O
14.		50x50x5	600	O

Oznaczenia:

S - rolki standardowe

O - rolki opcjonalne

S/O - do prac seryjnych niezbędne jest wyposażenie maszyny w rolki opcjonalne