
















CPS35				
Rodzaje profili		Wydajność [mm]	Średnica zwinięcia [mm]	Uwagi
1.		20x5 50x10	150 350	S/O
2.		20x5 90x15	180 400	S/O
3.		15 30	120 400	S/O
4.		25x15x1.5 50x30x3	200 1000	S/O
5.		20x20x1.5 50x50x3	200 1000	S/O
6.		20x20x3 50x50x8	200 350	S
7.		30x30x4 50x50x8	200 400	S
8.		30x15x3 80x45x6	250 400	S
9.		40x20x5 60x30x6	250 400	S
10.		50x25x5	800	S
11.		10 30	100 400	O
12.		1-1/2" (48.3x2.9) 60x2	350 500	O
13.		20x20x3 45x45x6	200 300	O
14.		40x40x6	350	O
15.		30x15x2 70x30x3	250 1200	O

Oznaczenia:

S - rolki standardowe

O - rolki opcjonalne

S/O - do prac seryjnych niezbędne jest wyposażenie maszyny w rolki opcjonalne